

Pneumatic // -0.95...60 bar



P40.2 Basic



P60 Solid

Your Advantages

Type	P40.2	P60
	• Testing, adjustment and calibration of all types of pressure gauges • 3 in 1: vacuum, low pressure and medium pressure calibration • Exact adjustment in the mbar range thanks to ultra-fine thread pitch and large volume control valve • Tool-free change between positive pressure and vacuum generation	• Like P40.2 • Single pneumatic hand pressure pump up to 60 bar

Technical Data

Type	P40.2	P60
Pressure ranges		
→ Negative pressure	-0.95 bar	-0.95 bar
→ Positive pressure	40 bar	60 bar
Pressure medium	Air	
Connections		
Reference pressure gauge	G¼	
Test sample	G¼ with quick coupling and pressure hose (1 m)	
Basic		
Dimensions	Approx. 240 x 170 x 50 mm	
Weight	Approx. 1.1 kg	
Solid		
Dimensions (case)	Approx. 450 x 370 x 110 mm	
Weight	Approx. 4.2 kg	
+ Adapter kit	Chrome-plated brass, G½, G¼, G¾, G½, ⅛ NPT, ¼ NPT, ½ NPT, M12 x 1.5, M20 x 1.5, G⅛, G¼	
+ Seal kit	PA flat gaskets and O-rings	

Order code

Type	Version	Order number
P40.2	Basic	EPPM040EBL0000
	Solid (incl. case and adapter)	EPPM0400BL0000
P60	Basic	EPPM060EBL0000
	Solid (incl. case and adapter))	EPPM0600BL0000